

BARGE MISTLEY
Fourth annual site report

	1997	1998	1999	2000
P1 – S1	3980	4190	4526	4745
P2 – S2	4410	4625	4906	5130
B1 – P1	2674		3000	3235
B1 – S1	2704		3120	3295
B1 – P2			3176	3380
B1 – S2			3256	3450
R2 – S24	2110	2110	2128	2180
R0 – S24	2280		2298	2320
R2 – P24	2550	2780	4568	4655
R0 – P24	2720		4800	4885
R0 – Z99			3796	2350
P24 – Z99			1132	2600
S24 – P19	6790		6666	6675
P24 – S19	7180		8530*	8650*
S19 – P19	5300		5342	5350
S24 – P24			6560*	6640*
C2 – P24			5323	5460

P1 and S1 Forward frame posts (port and starboard)
P2 and S2 Second frame posts (port and starboard)
P19 and S19 Forward corner of quarter board (port and starboard)
P24 – S24 Aft corner of quarter board (port and starboard)
B1 Top of stempost
R0 Centre of rudder post
R1 Nail projecting from top of centre of transom
Z99 End of stern most frame post

* Measurements not direct due to superstructure.